

Potlatch

AVESF

1,1,2


AVBAR

1,1,2

Potlatch Corporation
Pulp, Paperboard & Packaging Group
Idaho Division

P.O. Box 1016
Lewiston, Idaho 83501
Telephone (208) 799-0123

August 30, 1988



Mr. Steven A. Breithaupt
Senior Water Quality Analyst
Idaho Division of Environment
2110 Ironwood Parkway
Coeur d'Alene, Idaho 83814

Dear Mr. Breithaupt:

Enclosed are copies of the well logs and the well driller's map of the Avery site. The well logs should enable your hydrogeologist to characterize the soil conditions at the site.

Also enclosed is a copy of the results of oil and grease testing conducted to date by Potlatch. The greatest contamination appears to be near and east of the property line.

Our plan is to send this information to one or more site remediation contractors to obtain a bid on further site investigation and cleanup. We are concerned that further investigation and remediation be coordinated with whomever is responsible for the property east of us, as our efforts may be nullified if oil is allowed to seep onto our property after cleanup.

We believe a meeting between all concerned parties would be appropriate before we commence any additional work at the Avery site. Please let me know when it would be convenient to hold such a meeting.

Sincerely,

Wm. O. Dameworth
Environmental Engineer
North Idaho Units

WOD:ts

Enclosures

USEPA SF



1373301